Work Order ID 57402 April 6, 2010 2:23:24 PM						1					Page 1		
Revision ID:	D4010-1			Accept					Setup	Start Stop			
	Bearpaw 4/06/10 4/09/10	Start Qty: 12.0 Req'd Qty: 12.0			Cust Item I Customer:	ID:				Stop			
Approvals:	Process Pla	ın:	Date:	Tooling: SPC (Y/N):		ate:			Run	Start Stop			
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp	
Draw Nbr	· · · · · · · · · · · · · · · · · · ·	ision Nbr											
D4010 100 Thermoform Thermoforming Mac	Chine	HAND FINISHING T Memo Cut Blan	HERMOFORMING ks to fit frame size	0.00				· · · · · · · · · · · · · · · · · · ·				1004/08	<u></u>
105 HandThermo Hand Finishing There	rmoforming	Memo Dry Sheo Temp: Time IN	ot as per QSI022 ALEXTRA 250° 8:00 Pm A	0.00 0.00 pric 10./2010					_			BB 10/04/1.	こ
			8:00 Pm A	pric 10./2010 pric 12/2010								<u> </u>	7

April 6, 2010 2:23:24 PM

Required Date: 4/09/10



Page 2

Item ID:

D4010-1

Accept



Setup Start

Stop



Revision ID:

Start Date:

Item Name:

Bearpaw

4/06/10

QC:

Start Qty: 12.00

Req'd Qty: 12.00



Cust Item ID: Customer:

Reference:

		_	
Δn	nra	vals:	
4 x p	PIV	4 et 10 •	

Process Plan: ____

Date:

Date:

Tooling:

SPC (Y/N):

Date: Date: Run

Start

Qty

Stop



Sequence ID/

Work Center ID

Operation Description

Set Up/ **Run Hours** Draw Number

Plan Draw Rev. Code

Accept Qty

Reject Reject Number

Stamp

110



Thermoform

THERMOFORMING MACHINE

Memo

0.00

0.00

Thermoforming Machine

Thermoform as per Dwg. D4010-1 and Folio FTA067 using tool DT 9540

Dwg. Rev. Folio Rev.

120

Quality Control

QC2- Inspect parts off machine FAI/FAIB

0.00

Memo

0.00

Visually inspect for proper formation of each part

130

Quality Control

Memo

QC8- Inspect parts - second check

0.00



Page 3

April 6, 2010 2:23:25 PM

Item ID:

D4010-1

Revision ID: Item Name: Bearpaw

Start Date:

4/06/10

Start Qty: 12.00

Required Date: 4/09/10

Req'd Qty: 12.00



Accept



Setup Start

Stop



Cust Item ID: **Customer:**

Reference:

Approvals:

Process Plan:

Date: Date: **Tooling:**

SPC (Y/N):

Date:

Date:

Run

Qty

Start

Stop



Sequence ID/ Work Center ID

140

Thermoform

Thermoforming Machine

Operation Description Set Up/ **Run Hours** Draw Number

Draw Rev.

Plan Code

Accept Qty

Reject Reject Number

Insp. Stamp

HAND FINISHING THERMOFORMING

Memo

0.00

0.00

1-Trim & Drill to Finished Dimensions as per dwg D4010-1

2- Use wearplate jig DT9542 to transfer drill holes in bearpaw as per dwg and use 0.375" unibite to open holes to finish size.

3-DEDIM CHANEER HOLES LASING & FENTE COMMITTERSINK BIT Wh. 10/04/14.

145

HandThermo

Hand Finishing Thermoforming

Memo

Anneal trimmed & drilled product at 250 deg. F. for 75 minutes & allow to cool in oven.

No CHANSLE TO ROLLINGS (For the 130 outy) Dh. 10/04/14 Use weather to transfer dield holes as per dwg 4010-041 Use. O-tente counter sink to chamber outside of holes for everyours. HI CHAMPER HOUSE US MUG. O FENTIE COUNTERS INVE BIT 10/64/19 THE CHANGE

Dart Aerospace Ltd

.W/0: 5	7402	WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
poloyly		PERMENANT CHANGE ON ROLLING CARD.	wh	10/04/14	Q		Soloulis
10/04/14	140	Use wearban to transfordull holor, as Rondus 19010-041 Use & Frute counters with bit to chamfer outside holes. No Routing CHANGE (FOR THIS WO only)		. 1 /	12.		Solorlis

Part No: <u>D4010-1</u>	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
DATE STEP	OTED	Description of NC		Varification								
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector				
								-				
								L				
		`										

NOTE: Date & initial all entries

April 6, 2010 2:23:25 PM



Page 4

Item ID:

D4010-1

Accept

Setup Start

Revision ID:

Item Name: Bearpaw

Start Date: 4/06/10 Required Date: 4/09/10

Start Qty: 12.00

Req'd Qty: 12.00



Cust Item ID: Customer:

Reference:

Approvals:

Process Plan: _____

Date:

Tooling:

SPC (Y/N):

Date:

Date:

Run

Start

Stop

Stop



Sequence ID/

Work Center ID

150

Quality Control

Operation Description

QC2- Inspect parts off machine FAI/FAIB

Date:_

Set Up/ **Run Hours**

Draw Number

Draw Rev.

Plan Accept Code Qty

Reject Qty

Reject Number Stamp

Insp.

Memo

0.00

0.00

Check dimensions to ensure conformity to drawing tolerances.

160

Quality Control

QC5- Inspect part completeness to step on W/O

170

Packaging

Identify as per dwg & Stock Location:

Memo

Memo

0.00

0.00

Elir/4/15 D

Packaging

Page 5

April 6, 2010 2:23:25 PM

Item ID:

D4010-1

Revision ID:

Item Name: Bearpaw

Start Date:

4/06/10

QC:

Start Qty: 12.00

Required Date: 4/09/10

Req'd Qty: 12.00



Accept



Setup Start

Stop

Start

Stop



Cust Item ID:

Customer:

Reference:

Approvais:

Process Plan:

Operation

Description

Date:

Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Draw

Number

Draw

Rev.

Date:

Plan

Accept Qty Code

Reject Qty

Run

Reject Number

Insp. Stamp

Sequence ID/ Work Center ID

180

Quality Control

Memo

QC21- Final Inspection - Work Order Release

0.00

Picklist Print

April 6, 2010 2:23:23 PM

Work Order ID: 57402

Parent Item:

D4010-1

Parent Item Name:

Bearpaw

Comments:

IPP RevA: New issue DD verified by:EC

IPP Rev B. Improved process Add Step 105 (Drying) & 145 (Annealling) to

routings 10/03/31 DL

Component Item ID/ M-ALXTRAB-S.300

Replacement Mfg/

Purchased

Primary Bin No

Last

Route 100

Unit of sf

Qty on

Remaining 623.9800 89.7347

Start Date: 4/06/10 **Start Qty: 12.00**

Qty

Status

Required Date: 4/09/10

Required Qty: 12.00

Date

Page 1

Alextra ET 0 .300 sheet

Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

therm

DART AE	ROSP	ACE LTD		,	Wo	rk Order:	57402
Description		· · · · · · · · · · · · · · · · · · ·			Do.	rt Number:	D-4010-1
Description	n: 🔑	Spartan 40			га	rt Number.	t) · LO(U =1
Inspection	Dwg: /	D-4010 Rev:					Page 1 of 1
		FIRST AF	RTICLE INSF	ECTION	CHECK	LIST	
			First Article		Prototyp		
) C	
		TH	IERMOFORM	IING SE	CTION		
Descripti	on			Accept	Reject	Method of Inspection	Comments
Inside Radii	i less tha	an"		NA			
Shape Defir	nition			/			
Texture Ret				/			
Material imp	perfectio	ns such as bumps, o	cracks, voids,	/			
boratoming				**			
Measured b	by:	19 F				Date:	10/04/02
				,			
			TRIMMING	SECTIO	N		
Drawir	ng		TRIMMING			Method of	Comments
Drawir Dimens	_	Tolerance	T	SECTIC Accept	N Reject	Method of Inspection	Comments
Dimens	ion	مئه .	Actual Dimension				Comments
Dimens	ion "		Actual	Accept			Comments
Dimens /1.60 5.50	ion "	4 0.25	Actual Dimension	Accept			Comments
Dimens /2.60 5.50 9.50	ion '('' '' ''	4/2 0.25 4/2 0.30	Actual Dimension	Accept			Comments
Dimens /2.60 5.50 9.50	ion '('' '' ''	*/ 0.25 */ 0.30 */ 0.30 */ 0.30 */ 0.30	Actual Dimension	Accept			Comments
Dimens /2.60 5-50 9.50	ion ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	4 035 4 030 4 030 4 030 4 030 4 030	Actual Dimension	Accept			Comments
Dimens 12.00 550 9,50 11.81	ion ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	# 0.25 # 0.30 # 0.30 # 0.30 # 0.30 # 0.30 # 0.30	Actual Dimension	Accept			Comments
Dimens 12.00 550 9,50 11.81	ion ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	1/2 0.35 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30	Actual Dimension 11. 875" 5.5 9.5 11. 8.25 14. 7 20. 9 83. 25 24. 5	Accept			Comments
Dimens 12.60 5.50 9.50 11.81 14.63 9.09 93.2 24.6	ion '('' '' '' '' '' '' '' '' '' '' '' ''	1/2 0.35 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/4 0.35	Actual Dimension 11. 875" 5,5 4,5 11.825 14.2 24.5 24.5	Accept			Comments
Dimens 12.00 550 9,50 11.81	ion '('' '' '' '' '' '' '' '' '' '' '' ''	# 0.25 # 0.30 # 0.30 # 0.30 # 0.30 # 0.25 # 0.25	Actual Dimension 11.875" 5,5 9,5 11.805 14.7 20.9 43.25 24.5	Accept			Comments
Dimens 12.00 5.50 9.50 11.81 14.65 9.09 9.3.2 24.6 9.30	ion '('' '' '' '' '' '' '' '' '' '' '' ''	1/2 0.35 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/4 0.35 1/4 0.35 1/4 0.35 1/4 0.35	Actual Dimension 11. 875" 5.5 4.5 11. 825 14.7 14.7 14.7 14.5 24.5 2.25 0.980 1.36	Accept			Comments
Dimens 12.00 5.50 9.50 11.81 14.65 9.09 9.3.2 24.6 9.37	ion '(" " " " " " " " " " " " " " " " " "	1/2 0.35 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/4 0.35 1/4 0.35 1/4 0.35 1/4 0.35 1/4 0.35 1/4 0.35 1/4 0.35	Actual Dimension 11.875" 5,5 9,5 11.805 14.7 20.9 43.25 24.5	Accept		Inspection	Comments
Dimens 12.00 5.50 9.50 11.81 14.65 9.09 9.3.2 24.6 9.37	ion '('' '' '' '' '' '' '' '' '' '' '' ''	1/2 0.35 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/4 0.35 1/4 0.35 1/4 0.35 1/4 0.35 1/4 0.35 1/4 0.35 1/4 0.35	Actual Dimension 11. 875" 5.5 4.5 11. 825 14.7 14.7 14.7 14.5 24.5 2.25 0.980 1.36	Accept			Comments 10/04/14.
Dimens 12.00 5.50 9.50 11.81 14.65 9.09 9.3.2 24.6 9.37 Mea	ion '(" " " " " " " " " " " " " " " " " "	1/2 0.35 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.30 1/2 0.35 1/2 0.35 1/2 0.00 1/2 0.	Actual Dimension 11. 875" 5.5 4.5 11. 825 14.7 14.7 14.7 14.5 24.5 2.25 0.980 1.36	Accept		Inspection	
Dimens 12.00 5.50 9.50 11.81 14.65 9.09 9.3.2 24.6 9.37 Mea	ion '(" ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	# 0.25 # 0.30 # 0.30 # 0.30 # 0.30 # 0.25 # 0.25 # 0.25 # 0.25 # 0.25 # 0.00	Actual Dimension 11. 875" 5.5 4.5 11. 825 14.7 14.7 14.7 14.5 24.5 2.25 0.980 1.36	Accept		Inspection Date:	10/04/14.
Dimens 12.00 5.50 9.50 11.81 14.65 9.09 9.3.2 24.6 9.37 Mea	ion '(" '' '' '' '' '' '' '' ''	# 0.25 # 0.30 # 0.30 # 0.30 # 0.30 # 0.25 # 0.25 # 0.25 # 0.25 # 0.25 # 0.00	Actual Dimension 11. 875" 5.5 4.5 11. 825 14.7 14.7 14.7 14.5 24.5 2.25 0.980 1.36	Accept		Date:	10/04/14.

D4010-041 BEARPAW ASSEMBLY (407)

С	OPTIMIZ EASE M	мв	09.11.10			
В	REDESI WITH O TOLERA	мв	09.11.02			
Α	NEWIS	SUE			MB	09.10.22
REV.			T =	DESCRIPTION	BY	DATE
DESIGN	1		<u>_</u>	DART AEROSPA	ACE L	ID.
DRAWN	1	-	,	HAWKESBURY, ONTAR		
CHECK	ED	1	(5	DRAWING NO.		REV. C
MFG, A	PPR.		7_	D4010		SHEET 1 OF 3
APPRO	VED	1	Q.	TITLE		SCALE
DE APF	R.	7	-	TBEARPAW (407)		NTS
DATE	09.1	1.10		COPYRIGHT © 2009 BY DART A THIS DOCUMENT IS PROVIDE AND CONTION THE AND EXPRESS NOT TO BE USED FOR ANY PURPOSE OR CONTION OR COMMUNIC WRITTEN PERMISSION FROM DAIL AC	DON THE EXPRES	S CONDITION THAT IT IS



